

APPENDIX B – ASSET CONDITION CODES

Asset Condition is category A

| | |
|-----|---|
| A01 | Cut out currently operating hot (signs of overheating) |
| A02 | Service Cable currently operating hot |
| A03 | Defective/weakened fuse carrier contacts |
| A04 | Physical damage to cut out/service cable requiring immediate action |
| A05 | Visual indication of burning/smell of smoke/smoke |
| A06 | Audible sounds of arcing |
| A07 | Exposed live conductors (live or neutral) |
| A08 | Broken fuse carrier – access to live components |
| A09 | Exposed conductors – evidence of theft/vandalism/damage |
| A10 | DNO Earthing issues which present an immediate risk to Consumer/MO |
| A11 | Disconnected or severely damaged DNO earth terminal/protective conductor |
| A12 | Currently damaged and exposed asbestos components including meter boards |
| A13 | Visible possible airborne asbestos fibres present at the service position |
| A14 | Polarity identified as incorrect at DNO cut out |
| A15 | Immediate risk to the public or customer due to current service position location |
| A16 | Service position insecure and exposed to immediate weather damage |
| A17 | Risk of electric shock or electrocution |
| A18 | Risk of fire at service position |

Asset Condition is category B

| | |
|-----|--|
| B01 | Fuse Carrier welded in to cut out base |
| B02 | Cut out loose on meter board |
| B03 | Damaged/missing phase barriers |
| B04 | Damaged/broken cut out terminals - missing terminal screws |
| B05 | Non With-drawable fuses by design |
| B06 | Cut Out unable to accept 16mm meter tails |
| B07 | Meter tails need to be replaced but cannot be changed by competent staff |
| B08 | Unhinged metal cut out covers over un-insulated conductors |
| B09 | Asbestos boards/materials identified – no immediate risk |

Asset Condition is category C

| | |
|-----|---|
| C01 | Signs of overheating – no damage to cut out or premises |
| C02 | Signs of Bitumen Compound leaking |
| C03 | Small fuses ie less than 60A |
| C04 | Concern over phase rotation incorrect at cut out |
| C05 | Shared fuses/cut outs/neutral blocks |
| C06 | Metal Clad Cut Out |
| C07 | Seal Tags Broken on cut out |
| C08 | Cut out with a fused neutral |
| C09 | Damaged or missing service cable guard |
| C10 | Service cable in cavity |
| C11 | Asbestos barriers, insulation, fuse shields identified |
| C12 | Excessive vegetation growth |
| C13 | Unacceptable close proximity to gas service |
| C14 | Fed from distribution board – local/remote from meters |
| C15 | VIR/MICC lead in's to property |