

### DCUSA Issues Form (DIF)

This form should be used by parties to submit matters for consideration to DCUSA Standing Issues Group (SIG).

The completed form should be issued to [DCUSA@electralink.co.uk](mailto:DCUSA@electralink.co.uk).

Document Control	
Date Submitted	07/07/09
Issue Title:	Rota Block Identifiers Communication Method
Issue Number*:	001
Meeting Ref*:	07/09
Attachments:	None

*\*Assigned by DCUSA Secretariat*

Originator details	
Party Name	ScottishPower Energy Retail Ltd
Originator Name	Lorna Gibb
Party Category	<del>Distributor</del> / Supplier / <del>IDNO</del> / Other
Email Address	<a href="mailto:Lorna.gibb@scottishpower.com">Lorna.gibb@scottishpower.com</a>
Telephone Number	0141 568 3021

Nature of Issue
<p>DCP 010 introduced the requirement on all distributors to annually produce the rota block identifiers report. During the change process it was recognised that in the past the disk had been collated at a central source and that this should continue. However, as this central source is the ENA the data is only collated for DNOs not IDNOs. As such suppliers are now receiving the data for a variety of sources on differing platforms, causing unnecessary manual intervention and delaying the data updates.</p>

Solution Overview – if known	
Solution description:	All DNOs & IDNOs to provide the data to a central source for

	collation and distribution to suppliers.
Lead time for Implementation:	July 2010 as data is provided annually.