

Cross comparison between category C items and proposed asset information items

MOCOPA Guide to Service Termination Issue Reporting Category C items: Asset Condition Information		Corresponding Asset Condition Information Item in DCP235	Comments
C02	Signs of bitumen compound leaking		DNOs to consider if this item is required to be included in the asset information items
C03	Lower rating fuse or cut-out (less than 60A) or re-wirable fuse	Covered under 'Switch/Fuse Rating'	
C06	Metal encased cut-out	Covered under 'Switch/Fuse Gear Arrangement'	
C07	DB equipment unable to be effectively sealed		DNOs to consider if this item is required to be included in the asset information items
C11	Asbestos barriers, insulation, fuse shields identified in DB equipment		Other asset information items probably give clues to this so DNO might decide this items is not required.
C14	Fed from distribution board – local/remote from meters	Covered under 'Switch/Fuse Gear Arrangement'	
C15	DB cable into cut-out is VIR/MICC	Covered under 'Cable Type'	
C16	DB equipment mounted on asbestos board		DNOs to consider if this item is required to be included in the asset information items
	Shared fuses/cut-outs/neutral blocks (meter install completed)		This item is no longer in the C codes. DNOs are to consider if it is required to be included in the asset information items
	Shared fuses/cut-outs/neutral blocks (preventing meter installation work)		This item is no longer in the C codes. DNOs are to consider if it is required to be included in the asset information items
C01	This code is withdrawn		
C04	The code is withdrawn		
C05	This code is withdrawn		
C08	This code is withdrawn		
C09	This code is withdrawn		
C10	This code is withdrawn		
C12	This code is withdrawn		
C13	This code is withdrawn		