

Unhinged metal clad cutouts – MCCO



File name: 2c955469-4087-40ba-aeab-643eea97439d.JPEG




 <p>electricity north west Bringing energy to your door</p>	<p>WORK AT LV SERVICE TERMINATIONS</p>	<p>Procedure B07</p>
--	--	--------------------------

Appendix A

SERVICE TERMINATIONS SUBJECT TO RESTRICTIONS:

Cut-out which may only be worked on or changed (Sections 7 and 8 above inclusive) after the incoming cable has been made **Dead**, remotely.

Metalclad cut-outs whose fuse cover is not hinged (ISCO 3 Phase Cut-out , or similar)	
	
On this type of cut-out, the fuse cover is fixed by screws only and has no hinges to hold the cover captive to the body of the cut-out. The cover Shall not be removed unless the incoming supply has been made Dead . This is to guard against the risk of a flashover caused by the lid slipping when being removed and making inadvertent contact with Live metalwork inside the cut-out.	
Any cut-out with a detachable hinged fuse cover	

Different types/mix of main fuse carriers

